



Instructions for 3037-55



Included items:

- One (1) stainless steel base
- One (1) plastic drip tray
- One (1) maple carving board
- One (1) heat lamp
- One (1) 250W red bulb
- Four (4) wood screws for heat lamp base

Assembly Instructions

1. Remove stainless steel base from box and lay flat on table
2. Insert black, plastic drip tray into stainless steel base
3. Place the maple carving board onto the black drip tray and you are ready to go!

Assembly instructions for optional heat lamp

1. Place maple carving board on a flat surface
2. Align the base of heat lamp to the desired location on the maple carving board
3. Mark each of the four (4) holes on the base with pen or pencil
4. Remove heat lamp and drill pilot holes in marked locations with a 3/32 size drill bit
5. Align the base once again over the pre-drilled holes and use the four (4) included stainless steel screws to secure the heat lamp into place
6. Plug the heat lamp into an approved, 120V electrical outlet
7. Turn on the heat lamp with the switch conveniently located away from the heat source

If you have any questions, please call the Cal-Mil Customer Support Team—(800) 321-9069